ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W1701, W1681, W1683, W1697, W1691, W1064	NA	Anam Layout
Segment No.	**Total Length (m)**	
6/C-W1701/S013609	351.02	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	202.64	77.636711	13.050495	77.638042	13.050192	W1064	W1064
2	148.38	77.636697	13.050462	77.638037	13.050189	W1683	W1681

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Anam Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	2000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvement to Roads and Drains at Anam Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000042
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/22/2016-17	30/04/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2016	29/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
V. CHANDRAPPA		0.00
Phone No.	**E-Mail ID**	
9448447181		

Field Inspection Details

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1701, W1681, W1683, W1697,

Number of Trees	Any Other Information	Name
9		KRISHNAPPA

Date of Inspection	Remarks
26/11/2016	COMPLETED

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1701, W1681, W1683, W1697,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/11/2016	26/12/2016	COMPLETED
SE	VASU K M	26/11/2016	26/12/2016	COMPLETED
EE	YARAPPA REDDY	26/11/2016	26/12/2016	
AEE	J N LOKESH	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1701, W1681, W1683, W1697,